

Marketing Bulletin

BULLETIN NO: MB-0820 DATE: December 8, 2008 PAGE: 1 of 4

TO: All Weil-McLain Distributors and Agents

FROM: Mike Boyd - Product Marketing Manager

SUBJECT: Updated U-Control Software on Ultra Gas Series 3 Boilers

Weil-McLain implemented a rolling change last October when we updated the software on the Ultra Gas Series 3 boilers (software on both the U-Control module, part # 383-500-627 and the display board assembly, part # 383-500-629). This software update is a natural progression as we continue to identify ways to optimize boiler set up, operation and ease troubleshooting.

What is new in the software?

- "Supply Too Fast" terminology has been changed to "Temp Rise Too Quickly".
- Additional pre-pump time (default is 20 seconds) for each priority is now available under the time menu (temp rise too quickly is ignored during pre-pump time and zero is actually the standard pre-pump time (please set this to the time required to get the hot water back into the boiler from the system).
- Adjusted "Temp Rise Too Quickly" error requires the condition to be present for two consecutive readings to cause the auto-reset lockout.
- "Temp Rise Too Quickly" must now occur 5 times during the same heat cycle to cause a manual reset condition; this was previously 5 times since the boiler was powered.
- Priority switching has been improved-
 - Boiler switches to higher priority as soon as it becomes active and then begins max and min run times.
 - If priority has a post-pump time greater than zero, it will shut down the burner and post-pump before switching to the next temperature.
 - Maximum and minimum run time rules have been updated.
 - Min Run Time = 0 on any priority will now not let that priority run if another priority is calling for heat.

5 WAYS TO IDENTIFY IF AN ULTRA GAS SERIES 3 BOILER IS PROGRAMMED WITH THE LATEST SOFTWARE (Control V1.04, Display V1.03 - Rolling Change Released 10/08)

ONLY ONE of the following 5 identifiers needs to be present

1. CP NUMBER

Boilers with CP# 5923868 and higher (started on 10/30/08)

2. CRATE IDENTIFICATION

Boilers with the updated software are sprayed with a white dot on label sides of the crate (started spraying crates on 11/6/08 with CP# 5924420)





4. REPROGRAMMED MARKINGS



Reprogrammed control has a black dot on lower right hand corner of label

U-Control Module (service part # 383-500-627)

Reprogrammed display has a black dot on the green board, next to the bar code label



Display Board Assembly (service part # 383-500-629)

5. SOFTWARE ID ON ENERGIZED DISPLAY SCREEN *

ORIGINAL Software Versions Screen		SOFTWARE VERSIONS	
	DISPLAY V1.00 to V1.02	DISPLAY	V1.02
		MAIN MICRO	V1.00
SECO	OND MICRO V1.00 to V1.03	SECOND MICRO	V1.03
UPDATED Software Versions Screen		SOFTWARE VERSIONS	
	DISPLAY V1.03	DISPLAY	V1.03
		MAIN MICRO	V1.00
	SECOND MICRO V1.04	SECOND MICRO	V1.04
* To navigate to the "Software Versions" screen, you must press the top and bottom key pad buttons (12 & 6 o'clock positions) simultaneously and hold for 5 seconds to enter the contractor mode (Contractor Screen). Then choose the			
"Diagnostics" option, scroll down to the "Software Versions" option and enter.		PREVIOUS	

Updated software has a "PREPUMP TIME" option

SPECIAL NOTE:

If you mismatch an old control and a new display... you would see the pre-pump option, but could not save it.

If you use a new control and old display... you would have the 20 second prepump time defaulted, but could not adjust it.

PRIORITY 1 TIMES		
MAX ON TIME:	FTB	
BOOST INTERVAL:	OFF	
PREPUMP TIME:	20 SEC	
POSTPUMP TIME:	30 SEC	

If you have any questions, please contact your local Weil-McLain representative or area sales office.