



### **SUBJECT: Aqua Plus Recirculation Plug Removal Issue**

There have been some reported occurrences in the field where the recirculation plug in the Aqua Plus indirect-fired water heater has been difficult to remove (see pictures below). We have reduced the torque setting in mid-November, 2011- beginning with Aqua Plus serial number EO4916110001.

To remove the recirculation plug, use a 1/2" drive breaker bar. If more leverage is necessary, use a pipe extension. If the fitting will not break loose, or if the head of the recirculation plug strips out, the tank may be replaced under warranty.

**Recirculation Plug  
Water Inlet Tapping**

